Work Practices/Engineering Controls, EM 385-1-1

- 06 J Heat Stress
- 11 C. D. Temp Wiring and Grounding
- 12 Lock Out/Tag Out
- 13 Hand and Power Tools
- 16 M. Drilling

Work Practices/Engineering Controls, EM 385-1-1

- 21D. Ladders
- 22 K. Elevating Work Platforms
- 25 D. Trenching
- Appendix C Silica

Work Practices/Engineering Controls, not in EM 385-1-1

- On-site Laboratory Safety
- VOC control
- Dust control
- Temporary Structures
- Exposure Time Limitation

Heat Stress

Elevating Work Platforms

Drilling

Trenching

Lock Out/Tag Out

Temp. Electrical, Power Tools



Ladders



Silica

Temporary Structures

Dust Control

VOC Control

Laboratory Safety

- Need Picture

Exposure Time Limitations